











- de** Montageanleitung
- en** Mounting instructions
- fr** Instructions de montage
- sv** Monteringsinstruktion
- nl** Montage-aanwijzing
- it** Istruzioni di montaggio
- fi** Asennusohje
- es** Instrucciones de montaje
- da** Monteringsvejledning
- tr** Montaj talimatları

- Differenzdruckfühler**
- Differential Pressure Sensors**
- Sonde de pression différentielle**
- Differenstryckgivare**
- Drukverschilopnemer**
- Sonda di pressione differenziale**
- Paine-eroanturit**
- Sondas de diferencia de presión**
- Trykdifferensføler**
- Fark Basıncı Sensörleri**

QBM2030-..
QBM3020-..
QBM3120-..


 <p>1916208</p>	<p>QBM2030-..</p> 	<p>QBM3x20-..</p> 	<p>QBM3x20-..D</p> 
 <p>1910M04</p>	 <p>1916M03</p>	 <p>1916202</p>	
 <p>QBM2030</p> <p>1910Z11</p>		 <p>1910Z09</p> <p>1910Z10</p>	

QBM2030-.. QBM3020-..




1910z12

QBM3120-..



1910z12a




max. 1.5 mm²



1910z13


Zero Reset

1.




1910z15

2.




1910z14

3.



1910z16


QBM2030-..



1910Z01_01

DIP Switch	QBM2030-1U	QBM2030-5	QBM2030-30
	100 Pa	500 Pa	0...3000 Pa
	+/- 100 Pa	250 Pa	0...1500 Pa
	+/- 50 Pa	200 Pa	0...1000 Pa

QBM3x20-..




1916Z06

DIP Switch

QBM3x20-..



1916Z07 (lin)



1916Z07 (rad)



For additional information please refer to the following documents on the Internet:



<http://siemens.com/bt/download>

→ search for "QBM2030" or "QBM3020" or "QBM3120"